

To: jsw@statoil.com[jsw@statoil.com]
Cc: Blair, Michael[Michael.Blair@tetrattech.com]
From: Justice, James
Sent: Thur 7/24/2014 9:17:29 PM
Subject: Question on the Wellhead from the Eisenbarth Well Pad

Good Afternoon Mr. Swearman,

I apologize for not being able to touch base. I was the initial responding FOSC for the response and will be the point of contact for the remainder of the project.

Mr. Malone asked that I submit a request in an email to you. I wanted to see if you could provide the following information in regards to the well head assemblies removed from the Eisenbarth Pad

- 1) Any pictures taken by Wild Well, the company that conducted the metallurgical testing and/or Statoil documenting the conditions of the well head tree assembly and lubricator head.
- 2) The current location and disposition of the well head tree assembly. Are they staged at an off-site location, etc?

If you can provide the information as soon as possible, it would be greatly appreciated, especially in regards to 2). A subset of 1) would be helpful via email. If the complete file is large please send any media to my attention at the address below.

I would also like to speak to you tomorrow morning regarding the project timing going forward. If you can let me know a good time to reach you that would be much appreciated.

Thank you for your assistance and please let me know if you have any questions or concerns.

Thank you,

JJ Justice
On-Scene Coordinator
U.S. EPA Region 5
Emergency Response Branch
25063 Center Ridge Road
Westlake, OH 44145
Phone: (440) 250-1744
Fax: (440) 250-1750